LANDING GEAR & HYDRAULIC COMPONENT REPAIR & OVERHAUL

All Maintenance Manual Repairs TWIN COMMANDER

- ACCUMULATOR/REGULATOR
 - o EA1563
 - o 790230 Series / 4790230 Series
 - o Photo
 - o Overhauls Consists of
 - Options
- DRAG BRACE ASSEMBLY
- POWER BRAKE VALVE
- MLG AUXILLARY ACTUATOR
- LANDING GEAR INNER BODY
- LANDING GEAR OUTER BODY
- NOSE GEAR STEERING CYLINDER
- GEAR/FLAP SELECTOR VALVE
- BODY & BUSHING ASSEMBLY
- 9920
- UPLOCK ACTUATOR
- PISTON ROD
- NOSE GEAR FORK ASSY
- MLG FORK ASSY
- AXLE
- NOSE WHEEL BYPASS VALVE
- TC COMPONENT EXCHANGES list
- Call for a complete list of Twin Commander capabilities

EA1563 790230 Series / 4790230 Series ACCUMULATOR/REGULATOR

OVERHAUL CONSISTS OF:

- Disassembling & inspection all components
- Repairing various bores & surfaces in head to new dimensions
- Installing new regulating poppets, balls and seats as necessary
- Replacing all components that are worn beyond serviceable limits
- Installing all new seals
- Adjusting regulating and safety valves to required aircraft working pressures
- Testing to verify proper function of all operating parameters to higher standards than are called for by the aircraft maintenance manual
- Painting & replacing all external placards & warning tags



OPTIONSOverhaul Exchange

INSPECTION FEES APPLY

EA1570-501 / EA1570-502 DRAG BRACE ASSEMBLY



OVERHAUL CONSISTS OF:

- Complete disassembly and inspection of Drag Brace
- NDT components
- Repair or replace components as necessary
- Remove & treat minor corrosion
- Replace all arm and attach bracket bushings & line bore for arm alignment
- Replace bungees
- Prime & paint per customer requirements

OPTIONS

Overhaul Exchange

INSPECTION FEES APPLY



LEGACY

AVIATION SERVICES INC.

C.E. PAGE AIRPORT (KRCE) 1701A N. CIMARRON RD YUKON OK 73099 405.350.2100 405.350.7600 F WWW.LEGACY-AVIATION.COM

EA1808 Series 4790279 Series / 790279 Series POWER BRAKE VALVE

OVERHAUL CONSISTS OF:

- Repairing main bore of housing to new dimensions, if necessary
- Repairing piston if necessary
- Replacing poppet if necessary
- Installing new arm pivot bushings
- Replacing mounting nuts if necessary
- Installing all new seals
- Testing to more stringent requirements than the aircraft maintenance manual



OPTIONS

Overhaul Exchange

INSPECTION FEES APPLY



EA1568 EA1596/710022-501 **MLG AUXILLARY ACTUATOR**



OVERHAUL CONSISTS OF:


- Disassembling & inspecting all components
- Installing all new seals
- **Testing**

OPTIONSOverhaul

INSPECTION FEES APPLY

01/17/13 5

ED12394 Series / ES12394 Series LANDING GEAR INNER BODY



OVERHAUL CONSISTS OF:

- Inspection of part
- NDT
- Repair of areas listed below as necessary
- Install new bushing
- Prime & paint per customer requirements



OPTIONS


Overhaul Exchange

Repair Dia. A
Repair Dia. B/Surface D
Repair Dia. C
Repair Dia. D/Surface B
Repair Dia. E
Repair Dia. F
Repair Dia. G
Repair Seal Area
Repair Datum A
Replace Bushing-Dia. H
Strip & Paint

INSPECTION FEES APPLY



ED12402 Series ES12402 Series LANDING GEAR OUTER BODY



OPTIONS

Repair Diameter B Repair Diameter D Replace Trunion Bushings Paint

INSPECTION FEES APPLY



LEGACI

AVIATION SERVICES INC.

C.E. PAGE AIRPORT (KRCE)
1701A N. CIMARRON RD
YUKON OK 73099
405.350.2100
405.350.7600 F
WWW.LEGACY-AVIATION.COM

713096 Series 4713096 Series NOSE GEAR STEERING CYLINDER



OVERHAUL CONSISTS OF:

- Repairing main bore and shaft exit lands of housing if necessary
- Repairing end plug shaft exit land, if necessary
- Repairing piston / shaft assembly if necessary
- Installing all new seals
- Testing

OPTIONS Overhaul

INSPECTION FEES APPLY



AVIATION SERVICES INC.

C.E. PAGE AIRPORT (KRCE)
1701A N. CIMARRON RD
YUKON OK 73099
405.350.2100
405.350.7600 F
WWW.LEGACY-AVIATION.COM

790231-509 GEAR/FLAP SELECTOR VALVE




OVERHAUL CONSISTS OF:

- Inspect and repair or replace components as necessary
- Replace all O-rings
- Test

 $\frac{\mathbf{OPTIONS}}{\mathbf{REPAIR}}$

INSPECTION FEES APPLY

9920 BODY AND BUSHING ASSEMBLY





OVERHAUL CONSISTS OF:

- Complete inspection of the part
- Repairing Dia.s A and/or B
- Repairing drag link attach bore-Dia. C, if required
- Repairing centering pin bore-Dia. D, if required
- Restoring shimmy dampener collar groove
- Repairing steering bracket bolt holes
- Replace Trunion Bushing
- Repairing Trunion Bushing cross bores
- Prime and paint per customer request
- Installing new data tags on the exterior of the body

INSPECTION FEES APPLY

Options
OVERHAUL
REPAIR
EXCHANGE

EA1593 Series UPLOCK ACTUATOR



OVERHAUL CONSISTS OF:

- Clean and inspect
- Replace defective parts
- Reseal
- Test

OPTIONS Overhaul Exchange

INSPECTION FEES APPLY



ED11370-1 ED11370-501 PISTON ROD



OVERHAUL CONSISTS OF:


- Inspect
- NDT
- Restore ID & OD as necessary
- Restore black oxide coating

OPTIONS OVERHAUL

INSPECTION FEES APPLY



ES10054 NOSE GEAR FORK ASSY



OVERHAUL CONSISTS OF:

- Disassemble
- NDT components
- Repair or replace components as necessary
- Repair axle bores as necessary
- replace scissor bushing
- Remove & treat minor corrosion
- Reassemble
- Prime & paint per customer requirements

OPTIONS
OVERHAUL
Replace Fork
Replace Piston Rod

INSPECTION FEES APPLY

LUACI

AVIATION SERVICES INC.

C.E. PAGE AIRPORT (KRCE) 1701A N. CIMARRON RD YUKON OK 73099 405.350.2100 405.350.7600 F WWW.LEGACY-AVIATION.COM

ES12423-1 ES12423-501 MLG FORK ASSY

OVERHAUL CONSISTS OF:

- Disassemble
- Inspect & NDT components
- Repair or replace components as necessary
- Remove & treat minor corrosion
- Reassemble
- Prime & paint per customer requirements

OPTIONS
OVERHAUL
EXCHANGE
Replace Piston Rod
Replace or Repair Axle

INSPECTION FEES APPLY





LEGACY

AVIATION SERVICES INC.

C.E. PAGE AIRPORT (KRCE) 1701A N. CIMARRON RD YUKON OK 73099 405.350.2100 405.350.7600 F WWW.LEGACY-AVIATION.COM

ED10300-1 ED10300-501 AXLE



OVERHAUL CONSISTS OF:

- Inspect
- NDT
- Restore bearing races
- Cadmium Plate

OPTIONS OVERHAUL EXCHANGE

INSPECTION FEES APPLY

V-102 NOSE WHEEL BYPASS VALVE



OVERHAUL CONSISTS OF:

- Clean and inspect
- Replace defective parts
- Reseal
- Test

OPTIONS

Overhaul Exchange

INSPECTION FEES APPLY

Twin Commander Component Exchanges, Repairs & OH

Part Number	Description	Capabilities / Available
EA1563 / 790230 Series	Accumulator/Regulator	OH / Exch
EA1570-501	Drag Brace Assy, Left	ОН
EA1570-502	Drag Brace Assy, Right	ОН
EA1808 Series	Power Brake Valve Assy	OH / Exch
790279 Series	Power Brake Valve Assy	OH / Exch
EA1596 / 710022-501	MLG Aux Actuator	ОН
EA1568	MLG Aux Actuator	ОН
ED12394 Series	Inner Body	OH / Exch
ES12394 Series	Inner Body	OH / Exch
ED12402 Series	Outer Body	REP
ES12402 Series	Outer Body	REP
713096 Series	Nose Steering Actuator	ОН
790231-509	Gear Selector Valve	REP
9920	Upper Body	OH / Exch
EA1593 Series	Uplock Actuator	OH / Exch
ED11370-1	Piston Rod	OH / Exch
ED11370-501	Piston Rod	OH / Exch
ES10054	Nose Gear Fork Assy	ОН
ES12423-1	MLG Fork Assy	ОН
ES12423-501	MLG Fork Assy	ОН
ED10300-1	Axle	OH / Exch
ED10300-501	Axle	OH / Exch
V-102	Nose Bypass	OH / Exch

INSPECTION FEES APPLY